

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2063 Crows Landing**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	10.44	11/20/2014 11/20/2014	Richard Willoughby

LM Start	0.00	Rating **	A	Issue No.	12	
LM End	0.00	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Operations & Maintenance Manuals					°
						°
DWR ID	DWR_RD2063_01_s_2013_12					
Action/Comments						
Inspector Comments: The LMA maintains a copy of O & M manual on file at district office.						

No Photos

LM Start	0.00	Rating **	A	Issue No.	15
LM End	0.00	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment				°
					°
DWR ID	DWR_RD2063_01_f_2014_15				
Action/Comments					
Inspector Comments: The LMA maintains adequate flood fight supplies and equipment.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	21
LM End	0.00	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training				°
					°
DWR ID	DWR_RD2063_01_s_2013_21				
Action/Comments					
Inspector Comments: The LMA is prepared for flood response.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2063 Crows Landing**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	10.44	11/20/2014 11/20/2014	Richard Willoughby

LM Start	0.00	Rating **	A/W	Issue No.	27
LM End	10.58	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			37.478842 °	37.390455 °
				-121.044627 °	-120.941945 °
DWR ID	DWR_RD2063_01_s_2012_27				
Action/Comments					
Add appropriate gravel or road base. Grade and compact.					

No Photos

LM Start	0.02	Rating **	A/W	Issue No.	3
LM End	0.51	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.478550 °	37.471548 °
				-121.044603 °	-121.044553 °
DWR ID	DWR_RD2063_01_s_2012_3				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : FA\_2014\_RD2063\_112\_3\_20141103\_00001.jpg



Looking south at typical view of waterside and landside slopes.

LM Start	0.02	Rating **	A/W	Issue No.	2
LM End	0.51	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.478548 °	37.471545 °
				-121.044605 °	-121.044553 °
DWR ID	DWR_RD2063_01_s_2012_2				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2063 Crows Landing**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	10.44	11/20/2014 11/20/2014	Richard Willoughby

LM Start	0.14	Rating **	C	Issue No.	16
LM End	0.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.476855 °	37.475658 °
				-121.044622 °	-121.044603 °
DWR ID	DWR_RD2063_01_s_2012_16				
Action/Comments					
Prunings					

No Photos

LM Start	1.41	Rating **	A/W	Issue No.	36
LM End	1.41	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.463582 °	37.463582 °
				-121.032263 °	-121.032263 °
DWR ID	DWR_RD2063_01_s_2013_36				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	1.47	Rating **	C	Issue No.	8
LM End	1.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.462723 °	37.462303 °
				-121.032020 °	-121.031928 °
DWR ID	DWR_RD2063_01_s_2012_8				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2063 Crows Landing**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	10.44	11/20/2014 11/20/2014	Richard Willoughby

LM Start	1.54	Rating **	C	Issue No.	10
LM End	1.54	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.461762 °	37.461762 °
				-121.031822 °	-121.031822 °
DWR ID	DWR_RD2063_01_s_2012_10				
Action/Comments					
Repair the levee slope damaged by vehicle traffic and prevent access where possible.					

No Photos

LM Start	1.57	Rating **	A/W	Issue No.	4
LM End	1.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.461322 °	37.461322 °
				-121.031785 °	-121.031785 °
DWR ID	DWR_RD2063_01_s_2012_4				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	1.69	Rating **	A/W	Issue No.	11
LM End	1.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.459813 °	37.459813 °
				-121.032372 °	-121.032372 °
DWR ID	DWR_RD2063_01_s_2012_11				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA\_2014\_RD2063\_112\_11\_20141103\_00004.jpg



Looking east at squirrel holes on landside slope.

**\* Location**  
 LS : Land Side    N/A : Not Applicable  
 WS : Water Side  
 CR : Crown

**\*\* Rating**  
 A : Acceptable                      N : Not Inspected/Rated  
 M : Minimally Acceptable        C : Corrected  
 U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
 Ma : Maintenance Deficiency  
 Ob : Design & System Obsolescence  
 En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2063 Crows Landing**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	10.44	11/20/2014 11/20/2014	Richard Willoughby

LM Start	1.95	Rating **	C	Issue No.	117
LM End	1.95	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.456460 °	37.456460 °
				-121.033730 °	-121.033730 °
DWR ID	DWR_RD2063_01_s_2012_117				
Action/Comments					
Garbage					
Inspector Comments: Garbage at landside toe and berm.					

No Photos

LM Start	2.32	Rating **	C	Issue No.	1
LM End	2.52	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.451895 °	37.449892 °
				-121.030492 °	-121.028072 °
DWR ID	DWR_RD2063_01_s_2012_1				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	2.53	Rating **	C	Issue No.	13
LM End	2.56	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.449787 °	37.449432 °
				-121.027943 °	-121.027472 °
DWR ID	DWR_RD2063_01_s_2012_13				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Dense vegetation at landside toe.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

## Reclamation District No. 2063 Crows Landing

No Photos

No Photos

No Photos

Page 6 of 17

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2063 Crows Landing**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	10.44	11/20/2014 11/20/2014	Richard Willoughby

LM Start	3.20	Rating **	A/W	Issue No.	37
LM End	3.20	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.442400 °	37.442400 °
				-121.023095 °	-121.023095 °
DWR ID	DWR_RD2063_01_s_2013_37				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	3.41	Rating **	A/W	Issue No.	38
LM End	3.70	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.440438 °	37.436906 °
				-121.020487 °	-121.017835 °
DWR ID	DWR_RD2063_01_f_2012_38				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	3.55	Rating **	M	Issue No.	53
LM End	3.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.438697 °	37.438697 °
				-121.019232 °	-121.019232 °
DWR ID	DWR_RD2063_01_f_2014_53				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: Typical view of rodent holes on landward slope.					

Photo 1 of 1 : FA\_2014\_RD2063\_112\_53\_20141120\_00049.jpg



Looking north at typical view of rodent holes on waterward slope.

\* Location  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2063 Crows Landing**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	10.44	11/20/2014 11/20/2014	Richard Willoughby

LM Start	3.77	Rating **	A/W	Issue No.	29
LM End	3.82	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.436197 °	37.435732 °
				-121.016937 °	-121.016090 °
DWR ID	DWR_RD2063_01_s _ 2012_29				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA\_2014\_RD2063\_112\_29\_20141103\_00014.jpg



Looking at typical view of a squirrel hole on landside shoulder.

LM Start	3.96	Rating **	C	Issue No.	17
LM End	4.10	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.434403 °	37.432653 °
				-121.014298 °	-121.013327 °
DWR ID	DWR_RD2063_01_s _ 2012_17				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	4.71	Rating **	A/W	Issue No.	20
LM End	4.71	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.429892 °	37.429892 °
				-121.004768 °	-121.004768 °
DWR ID	DWR_RD2063_01_s _ 2012_20				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2063 Crows Landing**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	10.44	11/20/2014 11/20/2014	Richard Willoughby

LM Start	5.05	Rating **	C	Issue No.	119
LM End	5.11	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.428202 °	37.427518 °
				-120.999518 °	-120.999362 °
DWR ID	DWR_RD2063_01_s _ 2012_119				
Action/Comments					
Ditch Inspector Comments: Farmer removed irrigation ditch from landward toe.					

No Photos

LM Start	5.48	Rating **	C	Issue No.	32
LM End	5.48	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.422827 °	37.422827 °
				-121.001788 °	-121.001788 °
DWR ID	DWR_RD2063_01_s _ 2012_32				
Action/Comments					
Schedule repair of erosion site prior to the next inspection. Inspector Comments: Landowner removed irrigation system and repired erosion sites.					

No Photos

LM Start	6.05	Rating **	C	Issue No.	22
LM End	6.63	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.416235 °	37.411285 °
				-120.997563 °	-120.998188 °
DWR ID	DWR_RD2063_01_s _ 2012_22				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

**\* Location**  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2063 Crows Landing**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	10.44	11/20/2014 11/20/2014	Richard Willoughby

LM Start	6.09	Rating **	A/W	Issue No.	5
LM End	6.09	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.415887 °	37.415887 °
				-120.998083 °	-120.998083 °
DWR ID	DWR_RD2063_01_s_2012_5				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	6.15	Rating **	A/W	Issue No.	120
LM End	6.36	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.415488 °	37.413473 °
				-120.998988 °	-121.001680 °
DWR ID	DWR_RD2063_01_s_2012_120				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : FA\_2014\_RD2063\_112\_120\_20141103\_00030.jpg



Looking south at dense vegetation on landside toe.

LM Start	6.78	Rating **	A/W	Issue No.	41
LM End	6.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.411877 °	37.411725 °
				-120.995685 °	-120.995092 °
DWR ID	DWR_RD2063_01_s_2013_41				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2063 Crows Landing**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	10.44	11/20/2014 11/20/2014	Richard Willoughby

LM Start	6.89	Rating **	A/W	Issue No.	39
LM End	6.89	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.411785 °	37.411785 °
				-120.993548 °	-120.993548 °
DWR ID	DWR_RD2063_01_s_2012_39				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	7.48	Rating **	M	Issue No.	6
LM End	7.48	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.404377 °	37.404377 °
				-120.988852 °	-120.988852 °
DWR ID	DWR_RD2063_01_f_2014_6				
Action/Comments					
Tree or limb					
Inspector Comments: Fallen tree limbs at waterward toe.					

Photo 1 of 1 : FA\_2014\_RD2063\_112\_6\_20141120\_00051.jpg



Looking southwest at fallen tree limbs at waterward toe.

LM Start	7.69	Rating **	M	Issue No.	7
LM End	7.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.403516 °	37.403516 °
				-120.985718 °	-120.985718 °
DWR ID	DWR_RD2063_01_s_2012_7				
Action/Comments					
Trim trees over roadway to at least 12 feet above ground level.					

Photo 1 of 1 : FA\_2014\_RD2063\_112\_7\_20141120\_00052.jpg



Looking north at overhanging tree on landward slope.

**\* Location**

LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2063 Crows Landing**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	10.44	11/20/2014 11/20/2014	Richard Willoughby

LM Start	7.81	Rating **	A/W	Issue No.	23
LM End	7.90	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.402400 °	37.401563 °
				-120.984087 °	-120.982775 °
DWR ID	DWR_RD2063_01_s_2012_23				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	7.88	Rating **	M	Issue No.	9
LM End	7.88	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.401774 °	37.401774 °
				-120.983132 °	-120.983132 °
DWR ID	DWR_RD2063_01_s_2012_9				
Action/Comments					
Trim trees over roadway to at least 12 feet above ground level.					

No Photos

LM Start	8.06	Rating **	C	Issue No.	24
LM End	8.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.400930 °	37.401148 °
				-120.980157 °	-120.977320 °
DWR ID	DWR_RD2063_01_s_2012_24				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

